Best Practice for Cleaning Alaris System Devices

- Make sure the modules are separated
- Clean each module separately
- Make sure the instrument is turned off, unplug the power cord and wipe all of the exposed device surfaces



- Cleaning Solutions:
 - PDI (Purle Top) Super Sani-Cloth Wipes
 - \circ 0.1 Bleach Wipes (i.e. C Diff.)
- Follow the instructions on the solution time to leave it on the device surface.
- Confirm that the instruments are thoroughly dry before using them again.

